

Injectex[®] Fabrics and HexFlow[®] Matrix Selector Guide

Resin Transfer Moulding is a composite manufacturing method that allows high quality components to be produced without autoclaves. Large and complex parts can be achieved allowing a higher degree of part integration, with consequent reduction of assembly costs.



Injectex[®] Fabrics

product data

Weight gsm	Style	Weave	Weight rate		Fibre count		Reinforcement yarn		Standard Width cm	Thickness mm	Powdering
			Warp	Weft	Ch-Wp yarns/cm	Tr-Wt picks/cm	Warp	Weft			
CARBON FABRICS											
205	GB201	PLAIN	50	50	4.7	4.7	3K HS	3K HS	107	0.2	X
630	G1151	FORMABLE	50	50	7.4	7.4	6K HS	6K HS	100	0.6	X



HexFlow[®] Matrix

product data

	Monocomponent	Dry Tg	Service Temperature	Other Matrix Compatibility	Injection Windows	Viscosity
EPOXY						
RTM 6	X	196°C (385°F)	-60°C UP TO 180°C (-75°F UP TO 350°F)	YES (EPOXY)	UP TO 150 MIN AT 80°C (176°F)	≤ 100 mPa.s AT INJECTION DWELL
BMI						
RTM 651	X	285°C (545°F)	UP TO 232°C (UP TO 450°F)	YES (BMI)	UP TO 120 MIN AT 110°C (230°F)	≤ 120 mPa.s AT INJECTION WINDOW DWELL

The information contained herein is believed to be the best available at the time of printing but is given without acceptance of liability, whether expressed or implied, for loss or damage attributable to reliance there on. Users should make their own assessment of the technology's suitability for their own conditions of use and, before making any commitment with regard to the information given, should check that it has not been superseded.

For more information, please contact your nearest sales office, or visit our website at www.hexcel.com

